

F / G. 1



depressed regions


2/24

F / G. 2











F / G. 4B




F / G. 5





5/24


F / G. 6 A




F / G. 6 B











F / G. 9



F / G. 10









9/24


F / G. 12




F/G. 13A F/G. 13B F/G. 13C



F / G. 14







polishing time


polishing time

BL


D1 D2








F I G. 18A



F / G. 18B



the first stage (planarization)


14/24 F I G. 1 9




the second stage (surface material removal)



F / G. 20A




F | G. 20B




CODIESOS, DZBODI







16/24


## F / G. 22













F1G.24


19/24




F / G. 26A








F / G. 28



F / G. 29



130 133 143 101

F16.30